

G-III-B-124

ca. 1930

The Art Butler House
Private
Accident

The Art Butler House is a one and a half story, gable-roofed dwelling with a three-bay, center-door facade.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Art Butler House

2 LOCATION

STREET & NUMBER

West side of 219S at south end of Accident

CITY, TOWN

Accident

VICINITY OF

CONGRESSIONAL DISTRICT

6th

STATE

Maryland

COUNTY

Garrett County

3 CLASSIFICATION**CATEGORY**☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT**OWNERSHIP**☐ PUBLIC☒ PRIVATE☐ BOTH**PUBLIC ACQUISITION**☐ IN PROCESS☐ BEING CONSIDERED**STATUS**☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS**ACCESSIBLE**☐ YES: RESTRICTED☐ YES: UNRESTRICTED☒ NO**PRESENT USE**☐ AGRICULTURE☐ MUSEUM☐ COMMERCIAL☐ PARK☐ EDUCATIONAL☒ PRIVATE RESIDENCE☐ ENTERTAINMENT☐ RELIGIOUS☐ GOVERNMENT☐ SCIENTIFIC☐ INDUSTRIAL☐ TRANSPORTATION☐ MILITARY☐ OTHER**4 OWNER OF PROPERTY**

NAME

Arthur R. Butler

Telephone #:

STREET & NUMBER

CITY, TOWN

VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Garrett County Courthouse

Liber #: 392

Folio #: 606

STREET & NUMBER

Third and Alder Sts

CITY, TOWN

Oakland

Maryland^{STATE} 21550**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input checked="" type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Art Butler House is located on the west side of Rt. 219S at the south end of the town of Accident. The house is backed by trees.

The house is a one and a half story, gable-roofed dwelling with a three-bay, center-door facade. The facade points southeast and is covered by a shed-roofed porch. The porch roof forms a catslide with the roof of the house. On the northwest elevation is a shed-roofed kitchen wing.

The house rests on a coursed stone foundation and the walls are covered with horizontal boards. The windows are 1/1 sash, with drip mouldings and plain board surrounds. On the facade the windows have narrow upper sashes filled with leaded eights and large single lower sashes. The facade door has a transom. On either side of the S.W. and N.E. gable ends are small round-arched windows.

The roof is covered with asphalt shingles. At the center of the facade is a five-sided, hipped-roofed dormer. Three of its elevations have 1/1 sash windows. On the N.W. elevation is a gable-roofed dormer. The house has one interior stove chimney on the N.W. slope of the roof, attached to the dormer.

The interior arrangement features a center stair hall but is otherwise unknown.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

G-III-B-124

PERIOD**AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW**

<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES ca. 1930

BUILDER/ARCHITECT unknown

STATEMENT OF SIGNIFICANCE

This house is an excellent example of a late 1920's or early 1930's bungalow. The bungalow was a fashionable style for middle-class residences in the first years of the 20th century.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Ann Burns, Historic Sites Surveyor

ORGANIZATION

Maryland Historical Trust/Bureau of Mines

DATE

1981

STREET & NUMBER

Shaw House, 21 State Circle

TELEPHONE

(301) 269-2438

CITY OR TOWN

Annapolis

STATE

Maryland 21401

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

G-III-B

STATE OF MARYLAND
MARYLAND GEOLOGICAL SURVEY

KEYSERS RIDGE (JUNC. U. S. 40) 7.3 MI.
20' KAESSE MILL 2.3 MI.

5163 III NE
(ACCIDENT)

646

17'30"

647



McHenry, MD
USGS 7.5 Minute Series
Scale - 1:24,000
1947; photorevised 1974

Site #: G-III-B-124
Art Butler House
West side of Rt 219S, at south end of Accident
Accident



G-III-B-124

Art Butler House

Garrett Co., MD

Ann Burns 7/27/81

Facade - SE;NE elev.



G-III-B-124

Art Butler House

Garrett Co., MD

Ann Burns 7/27/81

NW & SW elevs.